

# ANGLE KIT

Little Glass Helpers

## TUTORIAL



Step 1: Remove the steel bar from the angle kit.



Step 2: Place two of the guides into the slots spaced slightly less than the size of the glass you are using.



Step 3: Place the steel bar across the guides. You may not need this for larger angles.




Step 4: Place your glass on the guides so that they are on either side of the bar.



Step 5: Solder along the joint and allow to cool.



Step 6: Turn your shape, add the next piece and solder the joint. Repeat until prism is finished.



Step 7: Use the angle kit to hold the glass parallel to your bench to get beautiful beading.



Step 8: Clean and pack away your kit holding it all together with a steel bar.